

**NORTH CENTRAL RAILWAY
JOINT SAFETY CERTIFICATE**

No 27/Poorva Exp (12381/12382)/GZB-MGS/NCR/2013

Based on RDSO speed certificate No. MC/LHB/Coach, dated 12.04.2012 (for all following mentioned LHB coaches except LS2 coach) and MC/LHB/Coach, dated 12.12.2012 (for second class Non AC EOG LHB coach LS2), certified that it is safe to permit regular operation of following Express train (12381/12382) by adding Second Class Non AC EOG LHB Coach (LS2) in place of LS coach in its existing composition of 22 nos. AC/Non AC EOG LHB variants coaches (LWRRM-2 + LWACCN-3 + LWACCW-02 + LWFCWAC-1 + LWSCN-11 + LWCBAC-01 + LS2-02 = 22 nos.) hauled by single WAP4/WAP5/WAP7 class locomotives over ALD-GZB (UP & DN) section of North Central Railway at a maximum speed of 130 kmph, subject to observance of all permanent and temporary speed restrictions already in force and /or those that may be imposed from time to time due to track, bridges, curves, overhead equipment and signaling & interlocking etc.

Train Nos.	Section	Proposed speed (kmph)	Sectional Speed (kmph)
Howrah - New Delhi Poorva Express (12381/12382) via GAYA	ALD-GZB (UP&DN)	130	130

The primary maintenance depot of 12381/12382 is at Howrah and the secondary maintenance depot is at New Delhi.

Further, Railway remarks on important para of RDSO speed certificate No. MC/LHB/Coach, dated 12.04.2012 (for all above mentioned LHB coaches except LS2 coach) and MC/LHB/Coach, dated 12.12.2012 (for second class Non AC EOG LHB coach LS2) are as under:

Speed Certificate Para No	Para of RDSO Speed Certificate	Railway Remarks
2.1	Track	
2.1.1	The track shall be to a minimum standard of 52 Kg rails on sleepers to M+ 7 density and depth of ballast cushion below sleepers of 250 mm, which may consist of at least 100 mm clean and the rest in caked up condition, on compacted and stable formation.	Minimum standard of track is 52 Kg (90 UTS) rails with sleepers to M+7 density & ballast cushion of 300/100 mm.
2.1.2	For track maintained to lower standard than that mentioned above, the Chief Engineer shall decide the lower maximum permissible speed on the basis of maintenance condition. When the Chief Engineer considers that the road bed is not compacted or there is improper drainage, he may suitably restrict the maximum permissible speed depending upon the local conditions.	The maintenance of ALD-GZB section comes under C&M-I Vol- I standard track.
2.1.3	The maximum permissible speed on curves shall be decided on the basis of existing provision of Indian Railways Permanent Way Manual Second Reprint-2004.	The maximum permissible speed on curves is as per Indian Railways Permanent Way Manual, reprint-2004.

2.1.3 of LS2 coach speed certificate	The maximum permissible speed on curves shall be decided on the basis of existing provision of Indian Railways Permanent Way Manual Second Reprint-2004 but should not exceed 110 kmph for curvature of track 2 degree and beyond 2 degree. However, in case of curve lower than 2 degree, maximum permissible speed will be 130 kmph.	The maximum permissible speed on curves is as per Indian Railways Permanent Way Manual, reprint-2004.
2.1.4	Joggled fish plating of welds should be done as per provisions of para 6.4 and para 6.6 of chapter-6 of USFD Manual and para 6.3 of AT welding manual and policy instructions of Railway Board. Fish plating of rail should also be ensured as per para 251 of IRPWM-2004 regarding maintenance of rail joints.	Ensured as per chapter-6 of USFD Manual and para 251 of IRPWM-2004.
2.1.5	(i) Replacement of existing loose heel switches by fixed heel curved switches laid on PSC sleeper layout with CMS crossings with adequate arrangements for designed geometry of turnouts shall be ensured. Turnouts with TWS shall be preferred on such routes.	On ALD-GZB section, all T/Outs are on PSC with curved switches.
	(ii) Preferably Improved SEJ shall be provided on such routes.	Noted
	(iii) Improvement on track geometry parameters on the route of operation of the coaches/trains shall be carried out.	Noted
	(iv) The curves shall have to be suitably realigned and proper transition length shall be provided.	Proper transition lengths exists for curves except for locations on mentioned in annexure-A of track certificate where PSR are imposed.
	(v) All level crossings shall be manned.	All LCs are manned.
2.1.5 of LS2 coach speed certificate	Zonal Railway may ensure further detailed examination of track as deemed fit based on age cum condition basis, overdue renewal and condition of formation etc. as per provisions of Chapter-III of IRPWM-2004 regarding permanent way renewals.	It will be ensured.
2.1.6 of LS2 coach speed certificate	The track maintenance shall be in accordance with the recommendations contained in RDSO report no. C&M-I, Vol.-I. In this connection, the instructions for the maintenance of track on high-speed routes circulated to the railways under RDSO's DO letter no. CRA/509 dated 07-07-1971 and approved by Railway Board vides letter no. 71/W6/HS/8 dated 27.08.1971 and 71/W6/HS/1 dated 21.10.1971 should also be followed	It will be ensured.
2.2	Bridges	
2.2.1	The clearance refers to bridges with standard design of girders, slabs, pipe culverts, piers and abutments, etc. issued by RDSO for BGML, RBG & MBG-1987 standard loadings. However, the bearings of span 78.8 meters (effective) designed for BGML standard loadings as per RDSO's Drg. No. BA-11154 should be strengthened by providing two additional anchor bolts.	Bearing of span 78.8 meters (effective) for BGML standard loadings has been strengthen by providing two additional anchor bolts.
2.2.2	Superstructures & bearings of non-standard spans including Arches and sub-structures of all bridges shall be examined under the directions of the Chief Bridge Engineer concern and certified safe by him in terms of current IRS Bridge Rules, Steel Bridge Code, Concrete	Superstructures & bearings of non-standard spans including Arches are safe

	Bridge Code, Arch Bridge Code, Bridge Sub-Structures and Foundations Code etc. read with up to date correction slips.					
2.2.3	The above clause has been arrived considering bridges are in physically sound condition. Zonal Railway shall certify the adequacy of bridges for permitting rolling stocks based on physical condition of bridges.	Bridges are in physically sound condition of ALD-GZB section.				
2.2.4	Location of bridges on which speed restrictions are imposed shall be notified by the Railways and incorporated in the working timetable.	There are no such bridges for imposed speed restrictions.				
2.2.5	This clearance is subject to the following parameters of locomotives and LHB AC/NON AC EOG variant coaches and Generator Van:					
(A)	For Locomotive:			Noted		
	SN	Description	WAP4		WAP5	WAP7
	1	Max. axle load	18.8+2% t		19.5±2 %t	20.5±2%t
	2	Max. tractive effort	30.8t		26.3t	32.9t
	3	Max. braking force at rail level	22.3t		16.3t	26.5t
4	Max. CG height from rail level	Not exceeding 1830 mm	Not exceeding 1830 mm	Not exceeding 1830 mm		
(B)	For LHB AC/Non AC EOG Coaches:					
	i) AC First Class Coach (LWFAC)					
	Maximum Gross Load	: 43.5t		Noted		
	Maximum Braking Force at Rail Level	: 5.8t				
	CG height above rail level	: Not exceeding 1830mm				
	ii) AC 2-Tier Sleeper Coach (LWACCW)					
	Maximum Gross Load	: 46.72t		Noted		
	Maximum Braking Force at Rail Level	: 5.8t				
	CG height above rail level	: Not exceeding 1830mm				
	iii) AC 3-tier Sleeper Coach (LWACCN)					
	Maximum Gross Load	: 48.8t		Noted		
	Maximum Braking Force at Rail Level	: 5.8t				
	CG height above rail level	: Not exceeding 1830mm				
	iv) AC (EOG) Pantry Car (LWCBAC)					
	Maximum Gross Load	: 48.2t		Noted		
	Maximum Braking Force at Rail Level	: 5.8t				
	CG height above rail level	: Not exceeding 1830mm				
	v) Generator Van (LWLRRM)					
	Maximum Gross Load	: 56.8t		Noted		
	Maximum Braking Force at Rail Level	: 6.62t				
	CG height above rail level	: Not exceeding 1830mm				
	vi) Non AG (EOG) 3-Tier Sleeper Class (LWSCN)					
	Maximum Gross Load	: 47.8t		Noted		
	Maximum Braking Force at Rail Level	: 5.8t				
	CG height above rail level	: Not exceeding 1830mm				


2.2.5 of LS2 coach speed certificate	The clearance is subject to the following parameters of Second Class Non AC EOG LHB variant Broad Gauge Coaches (LS2) (i) Maximum Axle Load : 16.25 t (ii) Maximum Braking force : 5.8 t (ii)Max. CG height from Rail Level: Not exceeding 1830 mm	Noted
2.2.6	Specific restrictions are applicable as mentioned in relevant speed certificates of hauling single/multiple locomotives issued by RDSO.	It will be ensured.
2.3	Signaling	
2.3.1	Provisions of GR, SR, SEM & all extant instructions issued from time to time shall be complied with.	Shall be complied
2.3.2	On the sections where EBD of more than 1 km is to be catered for, second distant signal or automatic signaling should be available failing which suitable speed restriction is to be imposed.	EBD of rolling stock is 979 m in adding composition of LS2 coach train.
2.4	Traction Installation.	
	IN 25 Kv AC OHE	
2.4.1	The 25 kV AC OHE shall have swiveling type of cantilever Assembly having the tension in the conductors regulated automatically, with a presage. The presage of 50/100 is on contact wire for a span of 72 m, proportionately less for smaller spans.	Swiveling type cantilever existing in the section.
2.4.2	In case of locations where 25 kV AC porcelain section insulators are installed on main line and lie within first 1/10 th and 1/3 rd of the span, immediately after the OHE structure and the runners are in trailing direction, the maximum speed shall be 120/h. At all other locations where 25 kV AC porcelain section insulators are installed, the speed shall be limited to 80 km/h.	Porcelain section insulators are not provided on main line.
2.4.2 of LS2 coach speed certificate	For DC OHE the condition of operation shall be specified by the CEE of the concerned Railways.	It will be ensured.
2.4.3	It is recommended that the cantilevers in the section should have BFB steady arm (RI No. 2390) with 25 mm Drop Bracket Assembly (RI No. 2360) instead of Tubular Steady Arm (RI No. 2520). Bent steady art at overlap locations shall continue.	BFB steady arm with 25 mm Drop Bracket Assembly has been provided on main line.
2.4.4	The current collection shall be made through one number pantograph fit for high-speed operation.	Current collection using Oliver "G" equipment is being done beyond 100 kmph.
2.4.5	In 25 kV AC traction area, the CEE of Railway shall have to ensure that the minimum height of contact wire and electrical clearances as stipulated in provision of Chapter-V and V-A, Electric Traction "Schedule of Dimensions of 1676mm gauge (BG) revised-2004" with latest Addendum & Corrigendum Slips are not violated and strictly followed to ensure its safe running.	Minimum height of contact wire and electrical clearances as stipulated in provision of Chapter-V and V-A, Electric Traction "Schedule of Dimensions of 1676mm gauge (BG) revised-2004" with latest Addendum & Corrigendum Slips are not violated
2.4.6	In addition to the above, the Chief Engineer of the concerned Railway may impose any temporary speed restriction on the basis of personal knowledge	Not required.

	experience of the Sectional OHE and the field conditions prevailing on the particular section.	
2.5	Rolling Stock	
2.5.1	Before starting the operation, CME/CEE of the concerned railway shall certify the track worthiness and safety of the rolling stocks. They shall also ensure proper maintenance of the stocks.	Proper maintenance of the stock will be ensured during primary maintenance before starting the operation.
2.5.2 of LS2 coach speed certificate	The Wheel Slide Protection (WSP) device of all the coaches in the rake shall be functional at the starting station. If the WSP of any coach become defective enroute, the brake system of that particular coach shall be isolated.	It will be ensured.
2.5.2	Railways shall ensure that at the originating station 100% brake cylinders are operative and WSP of all the coaches are functioning. If the WSP of any coach becomes defective en-route, the brake system of that particular coach shall be isolate. En-route, if required, brake system of not more than one coach may be isolated and minimum 95% brake power must be ensured.	It will be ensured.
2.5.3	Brake system of the locomotive and coaches shall be in proper working order.	It will be ensured.
2.5.4	The earthing arrangement on the coaches shall be maintained as per design.	It shall be ensured that earthing arrangement on the coaches shall be maintained as per design.
2.5.5	The LHB AC/Non AC EOG variant coaches shall be maintained as per the "Preventive Maintenance system for LHB Coaching Stock" issued by Railway Board and instructions issued by RDSO & Railway Board time to time.	Maintenance of LHB coaches is being done as per "Preventive Maintenance system for LHB coaching Stock" issued by Railway Board & RDSO from time to time.
2.6	General	
2.6.1	All the permanent and temporary speed restrictions in force and those that may be imposed from time to time due to track, bridges, curves, signaling and interlocking, etc. shall be observed.	Shall be observed.
2.6.2	Attention is also invited to the note on "Preparation of Electrical Equipment of Diesel and Electric Locomotives for high speed operation" circulated with this office letter No. EL/3.3.15/WAM2/Gr. CON dated 24.12.1970 and the locomotives should be attended accordingly.	Locomotive are attended as per mentioned letter.
2.6.2 of LS2 coach speed certificate	This coach infringes IR Schedule of Dimension (BG) revised – 2004, in respect of Clause No. 19 (b), 20 (b) of Chapter IV (A). Same infringements have already been condoned by Railway Board vide letter no. 2011/CEDO/SR/08 dated 28.03.2011 for Non AC Chair Car (EOG) LHB variant coach. Never the less, proposals for formal condonation in respect of the LS2 coach has been sent to CCRS vide RDSO's letter no. CT/DSH/3/Coaches, dated 03.12.2012. Commercial run of the coach may be done after receipt of formal condonation from Board.	Noted and Infringement (Form-XVII) certificate enclosed.


2.6.3	LHB FIAT design of AC/Non AC EOG infringes clause of IR SOD 1973/2004. Railway Board vide letters tabulated below has condoned the infringements.	Noted and Infringement (Form-XVII) certificate enclosed.	
S N	Type of Coach	Clause no. of IRS SOD 1973/IR SOD 2004	Railway Board Condonation letter no.
1	AC Chair Car (LWACCZ)	13(b), 16, 17, 19(b), 20(b), 21(b), 22 and 32(b) of Chapter IV(A) of BG, SOD, 1973	97/CEDO/SR/3, dated 07.02.97
2	Power Car (LWLRRM)	32(b) of Chapter IV(A) of BG, SOD, 1973	
3	AC three tier (LWACCN)	13(b), 16, 17, 19(b), 20(b), 21(b), 22, 31 and 32(b) of Chapter IV(A) of BG, SOD, 1973	2002/CEDO/SR/13 dated 10.12.2002
4	Non AC Sleeper class (LWSCN)	19(b), 20(b) of Chapter IV(A) of Indian Railway BG SOD, Revised 2004.	2011/CEDO/SR/1 04.10.2011.
5	Non AC Second class (LS2)	19(b), 20(b) of Chapter IV(A) of Indian Railway BG SOD, Revised 2004.	2011/CEDO/SR/08dt 28.03.2011
2.6.3 of LS2 coach speed certificate	Zonal railways shall ensure that the load of LS2 coach should not exceed more than its designed load i.e. 16T maximum (approx 200 passengers).	It will be ensured.	
2.6.4	The design of WAP4 locomotive infringes clause 9(b), 12 and 13 Chapter IV (C) of the BG Metric Schedule of Dimensions 1929 (Reprint-1973). These infringements have been condoned by Railway Board their letter No. 96/CEDO/SR/10 dated 10.05.1996.	Noted and WAP4 loco is already in operations of Rajdhani trains.	
2.6.5	The pantograph of WAP5 locomotive in locked down condition and the surge arrestors infringe the Maximum Moving Dimensions of 1929 over non-electrified sections. After removing the pantograph pan assembly and two surge arrestors, the profile will infringe the Maximum Moving Dimensions of 1929 but will be within 'X' class loco profile. For movement of the loco in non-electrified territory, pantograph can assembly and two surge arrestors shall be removed and the movement of the loco shall be cleared by the Railway concerned as per the extant rules applicable. In non-electrified section where Maximum Moving Dimensions of existing 'X' class locos are not permissible, the movement shall be in accordance with the instructions issued by Railway Board and other additional instructions issued by the Zonal Railways for the movement of ODCs. Railway Board	Noted, ALD-GZB section is fully electrified.	

	have condoned these infringements of WAP5 locomotives vide their letter no. 95/CEDO/SR/18, dated 14.07.1995.	
2.6.6	The pantograph of WAP7 locomotive in locked down condition and the surge arrestors infringe the Maximum Moving Dimensions of 1929 over non-electrified sections. After removing the pantograph pan assembly and two surge arrestors, the profile will infringe the Maximum Moving Dimensions of 1929 but will be within 'X' class loco profile. For movement of the loco in non-electrified territory, pantograph can assembly and two surge arrestors shall be removed and the movement of the loco shall be cleared by the Railway concerned as per the extant rules applicable. In non-electrified section where Maximum Moving Dimensions of existing 'X' class locos are not permissible, the movement shall be in accordance with the instructions issued by Railway Board and other additional instructions issued by the Zonal Railways for the movement of ODCs. Railway Board have condoned these infringements of WAP7 locomotives vide their letter no. 2000/CEDO/SR/2, dated 17.02.2000.	Noted, ALD-GZB section is fully electrified.
2.6.7	The adequacy of the brake power available on the locomotives in conjunction with the coaching stock to be used in the proposed train, vis-à-vis the signalling system available on the route, shall have to be established.	It will be ensured.
2.6.8	Concerned Railways shall provide fencing as per their assessment to prevent unauthorized pedestrian/cattle crossings.	It will be ensured.


(S.K.Ahmad) 22/1/14
Chief Mechanical Engineer


(A.K.Rawal) 22/1/14
Chief Electrical Engineer


(M.GARHWAL) 08/01/2014
Chief Signal & Tele. Engineer


(U.K.Singh)
Chief Operations Manager


(Satish Kumar) 27.1.2014
Principal Chief Engineer

**NORTH CENTRAL RAILWAY
BRIDGE ENGINEER'S CERTIFICATE**

Based on RDSO's speed certificate nos. MC/LHB/COACH dated 12.04.2012 and MC/LHB/COACH dated 12.12.2012, certified that bridges on the sections given below are having minimum strength of super structure as indicated against the sections as per revised Bridge Rules -1964 and are safe for running of LHB trains comprising of 22 nos. AC and Non AC EOG LHB variant coaches hauled by single WAP-4/WAP-5/WAP-7 class of locomotives, up to the maximum speed indicated against the sections, subject to all temporary & permanent speed restrictions already in force and those that may be imposed from time to time.

Section		Line	KM		% Strength	Max. Speed
From	To		From	To		
MGS	GZB	UP/DN	677.28	1428.50	100% RBG	130 Kmph

Sub structure of all the bridges on the sections given above are in satisfactory condition and are safe for running of LHB trains comprising of 22 nos. AC and Non AC EOG LHB variant coaches hauled by single WAP-4/WAP-5/WAP-7 class of locomotives, up to the proposed speeds conforming to the provisions of revised IRS Bridge Sub structure and Foundation code-1985.

This clearance is subject to the following parameters of locomotives, LHB AC/Non AC EOG variant coach and Generator van -

SN	Parameters	Locomotive		
		WAP4	WAP5	WAP7
1.	Max. Axle load	18.8 + 2% t	19.5 + 2% t	20.5 + 2% t
2.	Max. tractive effort	30.8 t	26.3 t	32.9 t
3.	Max. braking force at rail level	22.3 t	16.3 t	26.5 t
4.	Max. G.G. height from rail level	Not exceeding 1830 mm		

SN	Parameters	LHB AC / Non AC (EOG) coaches						
		AC First Class coach (LWFAC)	AC 2-tier Sleeper Class coach (LWACCW)	AC 3-tier Sleeper Class coach (LWACCN)	AC Pantry Car (LWCBAC)	Generator van (LWLRRM)	Non AC 3-tier Sleeper Class (LWSCN)	Non AC Second Class (L.S)
1.	Max. Gross load	43.5 t	46.72 t	48.8 t	48.2 t	56.8 t	47.48t	56.5t
2.	Max. braking force at rail level	5.8 t	5.8 t	5.8 t	5.8 t	6.62 t	5.8t	5.8t
3.	CG height above rail level	Not exceeding 1830 mm	Not exceeding 1830 mm	Not exceeding 1830 mm	Not exceeding 1830 mm	Not exceeding 1830 mm	Not exceeding 1830 mm	Not exceeding 1830 mm

This clearance is subject to the following parameters of second class Non AC EOG LHB variant BG coaches (LS2)-

1.	Maximum axle load	16.25t
2.	Maximum Bracking Force	5.8t
3.	Max. CG height from rail level	Not to exceed 1830 mm.

The specific restrictions are applicable as mentioned in the relevent speed certificates of hauling single/multiple locomotives issued by R.D.S.O. Speed restriction of 50 Kmph from substructure point of view to be observed on bridge no. 503 (UP/DN) at location 725/27-29 of block section PRE-JHG on MGS-ALD section of Allahabad Division.

Countersigned


(Ramesh Chandra)
Chief Bridge Engineer


(R. S. Rajpal)
Dy.CE/Bridge/IQ

**NORTH CENTRAL RAILWAY
TRACK CERTIFICATE**

Certified that track on the following sections of North Central Railway, the weakest portion of which as per details given under is to the required strength, which can safely permit for 'Running of Trains comprising of 22 nos. AC/Non AC LHB variants coaches indicated against each section as under, subject to observance of all temporary and permanent speed restrictions (as mentioned in Annexure 'A') in force and/ or imposed from time to time on various accounts. All conditions stipulated in RDSO's speed certificate no. MC/LHB/COACH dt. 12.04.2012 & 12.12.2012 for tracks is fulfilled except for C&M I (Vol.I) standards which are met with in about 85% length of track.

Line	Section		Kms		Rails		Sleepers			Ballast cushion (in mm) Total/Clean	Max. speed proposed (kmph)	Max. sectional speed existing in the section (kmph)
	From	To	From	To	Type	% of wear or year of laying	Type	Year of laying	Density			
DN	GZB	MGS	1428.50	677.28	52 Kg,90 UTS	2002	PSC-5	1984	M+7	300/100	130	130
UP	MGS	GZB	677.28	1428.50	52 Kg,90 UTS	1991	PSC-5	1991	M+7	300/100	130	130

Countersigned

(Signature)
18/11/13

(S.N. Agrawal)
CTE

(Signature)
18/11/13
(S.K. Srivastava)
Dy.CE/TP

PERMANENT SPEED RESTRICTIONS (MGS-GZB) UP LINE

S.N.	Between Station	Location		S.R	Proposed reason
		From	To		
MGS-ALD UP LINE					
1	KYT -CAR	701/23	702/5	100	Unusual vibration on bridge no. 479
2	KYT -CAR	704/5	705/19	100	Inadequate transition length on curves
3	PRE-JHG	725/27	725/29	50	Physical condition of Br. 503 unsatisfactory
4	MZP-BDL	742/23	743/27	100	Inadequate transition length on 0.50° curve
5	BEO-GAE	749/9	754/3	100	Inadequate transition length on curve (1.16° & 0.45°)
6	NYN-ALD	824/3	824/23	60	Non transitioned curve(1.25°) on approach of Bridge.
7	ALD-YD	824/1025	824/09	10	1 in 8.5 double slip diamond on loop line
ALD-CNB UP LINE					
8	ALD-SFG	826/03	827/07	75	1 in 12 T/out taking off from outside of 2° curve
9	SFG-BMU	828/5-7	829/3-5	75	1 in 12 T/out taking off from inside of 1.2° curve
10	CNBI-YD	1015/17	1016/DL-5	40	Negotiation 1 in 12 cross-over
11	CNBI-CNB	1016/DL-5	1018/DL-45	50	Poor visibility due to curve 2° to 3°
12	CNBI-CNB	1018/DL-45	1019/DL-01	30	Poor visibility and heavily populated area
13	CNBI-CNB	1019/3	1019/7	15	Due to 1 in 8.5 T/out in yard.
CNB-TDL UP LINE					
14	CNB-YD	P.F.No.2,3,4,5,6 & 7		10	Negotiating double slip diamond of 90R 1 in 10.
15	CNB-GOY	1019/10A	1019/17	65	Single slip diamond in curve no.90 in GMC yard.
16	JUHI-W	1021/09	1021/15	15	Negotiating Diamond Crossing for movement via North to DN yard
CNB-TDL UP LINE (3rd line)					
17	CNB-GOY	1019/23A	1019/37A	30	Negotiating 1 in 12 Cross over
18	CNB-GOY	1020/13A	1020/17A	65	Inadequate transition length on 4° curve
19	GOY-PNK	1025/15A	1025/29A	65	Inadequate transition length on 4° curve
20	GOY-PNK	1028/07	1028/09	30	New turnout
CNB-TDL UP LINE					
21	ETW-YD	1156/19	1156/25	110	Inadequate transition on 0.50° reverse curves
22	MNR-YD	1222/17	1222/25	120	1 in 12 T/out taking off from outside of transition portion of 0.50° curve
TDL-GZB UP LINE					
23	TDL-Yd	1247/29	1250/15-17	65	Double slip diamond xings on approach of 1.75° curve
24	TDL-Yd (Loop Line)	1247/29	1247/33	15	Negotiating 1 in 8.5 diamond for loop line
25	TDL-Yd	1248/9	1248/39	30	Damaged washable apron
26	TDL-Yd	1249/17A	1249/35A	65	Inadequate transition length due to sharp reverse curve.
27	ALJN-Yd	1326/3	1326/7	100	Poor visibility due to 0.38° curve and heavily populated area

CTE

Dy. CE/TP

PERMANENT SPEED RESTRICTIONS (GZB-MGS) DN LINE					
S.N.	Between Station	Location		S.R	Proposed reason
		From	To		
GZB-TDL DOWN LINE					
1	ALJN	1327/4	1326/28	100	Poor visibility due to 0.35° curve and heavily populated area.
2	MTI-TDL	1250/16	1247/30	65	Double slip diamond xings on approach of curve
3	MTI-TDL	1248/40	1248/14	30	Track is weak due to bad drainage.
TDL-CNB DOWN LINE					
4	SKB-YD	1212/34	1212/26	110	1 in 12 & 1 in 8.5 T/outs taking off from inside & outside of transition portion of 0.25° curve.
5	SKB-YD	1211/26	1211/14	120	1 in 12 T/outs taking off from inside & outside of transition portion of 0.50° curve.
6	ETW-YD	1156/18	1156/14	110	Inadequate transition length on 0.63° reverse curves
7	PNK YD	1029/16	1029/02	110	T/outs taking off from inside/outside of 0.28° curve and inadequate transition length
TDL-CNB DOWN LINE (4th line)					
8	PNK-CNB	1026/30A	1019/28	75	Sectional speed
9	PNK-GOY	1026/32A	1026/30A	30	New turnout
10	GOY-CNB	1020/16A	1019/2A	65	Inadequate transition length on 4° curve
TDL-CNB DOWN LINE					
11	JUHI/E	1019/20	1019/12	65	Diamond Xing on curve as per IRPWM para 416.
12	JUHI/C	1020/26	1020/20	15	South line use for down traffic.
13	STN/CNB	1019/2	1019/4	15	Due to X-ing for North line to South line.
14	CNB Yd	P.F. No. 1,2,3,4,5&6		10	1 in 10 double slip diamond
15	JUHI/W	1021/18	1021/10	10	Negotiating double slip diamond crossing.
CNB-ALD DOWN LINE					
16	CNB-CNBI	1019/DL-2	1018/DL-46	30	Poor visibility & heavily populated area
17	CNB-CNBI	1018/DL-46	1015/DL-42	50	Poor visibility due to curve 2° to 3°
18	CNB-CNBI	1015/DL-42	1015/12	40	Negotiating 1 in 12 cross-over.
19	SFG Yard	830/0	829/26	120	Inadequate transition length between reverse curves.
20	SFG Yard	829/6	828/6	110	1 in 12 T/out taking off from inside & outside of 1.34° curve.
21	SFG-ALD	827/8	826/06	85	1 in 12 T/outs taking off from out side of 2° curve
22	ALD-Yard	825/30	825/06	30	Damaged washable apron.
23	ALD-Yard	824/24	824/4	60	Inadequate transition length on 1.25° curve
ALD-MGS DOWN LINE					
24	ALD-NYN	824/14	824/10	10	1 in 8.5 double slip diamond on loop line
25	NYN-COI	816/38	815/38	125	1 in 12 T/out taking off from inside/ out side of 1.05° curve.
26	MZP-Yard	736/16	735/12	90	Non transitioned curves of 1.5° & 1°
27	PRE-JHG	725/30	725/28	50	Physical condition of Br. 503 unsatisfactory
28	DAP-CAR	705/20	704/20	100	Inadequate transition length of curves
29	CAR-Yard	705/18	705/04	65	Inadequate transition length between two reverse curves of 0.50° and 1 in 8.5 double slip diamond
30	CAR-Yard	705/10	705/08	10	Negotiating 1 in 8.5 diamond crossing for loop line
31	CAR-KYT	702/6	701/24	100	Unusual vibration on bridge no. 479

L2/18/11/13
CTE

18/11/13
Dy.CE/TP