

Details of Train Accidents 2018-19

A. Details of Consequential Train Accidents

1	25.04.18	JAG C-2	MLC (Moth-Erach Road) - Tractor Trolley dashed with train no. E/BCN at MLC No. 155/E between Moth-ERC of JHS Division. Report submitted/accepted by DRM/JHS on 26.04.2018. (01 outsider Killed, 05 Grievous, 07 Simple injury) Cause: Gate was in open condition during passing of train. (Careless working of gateman.)
		JHS	
2	21.05.18	SAG B-3	Fire (Birlanagar) - in coach no. B-7 (ECoR 153154) & B-6 (NR 07932) in at Birla Nagar in train no. 22416 AC AP Express. Cause: Due to inadvertent throwing of cigarette butt or match sticks by some passenger using the toilet.
		JHS	

B. Details of Non-Consequential Train Accidents

Indicative (5)			
1	14.06.18	JAG H-1 PRYJ	SPAD (Ajaibpur Station) - Loco Pilot Sh. R. K. Bharadwaj/GZB of train no. 64109 Dankaur-Shahibabad EMU passenger overshot Starter signal of 3 rd line at AJR in ON position. Cause:- Careless working of Moterman. (Crew –NR) (Distance crossed – 102 meter)
2	15.08.18	JAG H-1 AGC	SPAD (Chiksana Station) - Loco Pilot&Asth. Loco Pilot of train no. 15631 Exp.overshot Starter and Advanced Starter Signal of Chiksana station in ON position. Cause:- Careless working of LP and ALP. (Crew – NWR) (Distance crossed-1400 meter)
3	30.11.18	JAG H-1 AGC	SPAD (Bhandai Station) - Train No. 51882 AGC-GWL Passenger left AGC at 07.00 Hrs. &overshot the home signal at Bhandai station at 07.17Hrs. Cause:- Careless working of LP and ALP. (Distance crossed- 7 meter)
4	17.01.19	JAG H-1 AGC	SPAD (Mora Station) - Train no. 54792 up passenger overshoot the home signal no 19 of MORA station in ON position. Cause:- Careless working of LP and ALP. (Crew-NWR) (Distance crossed – 332 Meter)
5	02.03.19	JAG H-1 AGC	SPAD (IDH Station) -Train no. 15632 Exp. overshot Intermediate Starter Signal no. 20 of IDH station in ON position at 05.33. Cause:- Careless working of LP and ALP. (Crew-NWR) (Distance crossed –20 Meter)
Other Train Accident: (13)			
1	28.04.18	Sr. Sub. D-5 AGC	Derailment(MTJ-Bhaisa) - E/BCN Spl departed from Mathura branch line no. 04 at 18.25 hrs. Train was passing under the ROB, suddenly two cattle dashed the engine from right side and one wagon next to engine got derailed at Km no. 353/07. Cause:- Due to CRO.
2	08.05.18	Sr. Sub. D-5 AGC	Derailment(Yamuna Bridge Yard) - E/Box goods train started from L.N. 07 at 10.47 hrs, about 10.50, LP reported that pressure of engine dropped while guard and ALP checked the load and found two no. box 25th & 26th fro engine were derailed. Cause:- Due to wagon defect.
3	27.05.18	Sr. Sub. D-5 PRYJ	Derailment(Firozabad Yard) - While entering in DN loop line 7 wagons of train MDN goods derailed at FZD at 09.03 hrs DN Main line and DN Loop line block. Cause:- Due to rail weld fracture.

4	20.06.18	Sr. Sub. D-5 PRYJ	Derailment (Chunar Yard) - While arriving in line no. 7 of CAR yard coming from MGS, 2 wagons 8th no. 35261710030 NC derailed by DE trolley DE wheel & 12th No. 352617100115 NC derailed by DE trolley DE wheel from engine of train UP CMLK. Cause:- Due to climbing of wheel set of culprit wagon at point no 223 & sharpness of curvature, presence of cluster of 1:85 turnout of the track in line no 7.
5	22.07.18	Sr. Scale D-5 PRYJ	Derailment (GMC Yd.) -While entering of train no. UP DMT in Line no. 28 of GMC yard. HWH end trolley both wheel of wagon no. WCR 56160966526 17th from loco derailed ahead of Point no. 32. Cause:- Due to entanglement of open flap door of culprit BRN wagon with adjoining rear wagon.
6	28.07.18	Sr. Sub. D-5 PRYJ	Derailment (SFG Yd.) -During receiving in UP loop line no. 7, derailment of BRN 99020293745 ER of train no. DMT Spl. at SFG yard. Cause:- Due to Uneven loading of ballast.
7	29.09.18	Sr. Sub. C-7 JHS	UMLC (Gwalior NG.) - Dashing of train 52171 with one tractor loaded with stone at UMLC No. 40 in GWO-SOE NG section. Cause -Due to negligence of Tractor Trolley driver.
8	22.10.18	Sr. Sub. D-5 JHS	Derailment (Murena Yd.) - Derailment of 2 BOBYN between Murena-Sank. Section. Cause:- Due to poor maintenance of track and wagon.
9	31.10.18	Sr. Sub. D-5 PRYJ	Derailment (Panki Yd.) - DMT loaded wagon No. SWR 004476 derailed at 15.45 hrs by DLI end trolley DLI end pair of wheel at trap point No. 288a during unloading ballast in longer loop in traffic block 13.55-15.55 hrs. Cause:- Due to excessive push back of train during unloading of ballast.
10	14.11.18	Sr. Sub. D-5 PRYJ	Derailment (Khurja Yd.) - While reception in line no.14 in KRJ yard, crew of UP train No. ARIK goods overshot UP Starter Signal no.9 and broken sand hump. DP no. 12322/WDG4/SBI and one BLCA wagon No. 61370808171 derailed at 19.35 hrs by leading trolley with all wheels. Cause:- Disregard of signal by the crew.
11	14.12.18	JAG D-5 PRYJ	Derailment (Shikohabad Yd.) - Derailment of two wagons from EP of train no. DN GN 134 Goods. Cause:- Due to dropping of Auxiliary Reservoir supporting bracket of 18th wagon no. from EP.
12	22.01.19	Jr. Scale D-5 JHS	Derailment (Lalitpur station) -Derailment of one wagon of train no E/BOXNHL next to brake van at Km no. 1036/15. Cause:- Door of the wagon broken & came on the track, consequently the said wagon derailed.
13	05.02.19	Sr. Scale D-5 PRYJ	Derailment (Shikohabad station) – Derailment of 1 wagon of train no. DR-6 at SKB yard near point no. 298 A. Cause:- Due to CRO.
Yard Derailment: (22)			
1	18.04.18	JAG B-7 JHS	Fire (AIT yd.) in coach no. NC 95403 GS in AIT yard in train no. 51868 AIT-Konchh Shuttle. Cause:- Due to lit Bidi thrown by unknown person on the garbage of coach.
2	22.04.18	Sr. Sub. D-6 PRYJ	Derailment (ALD Yard) - While shunting dead DSL locomotive no. 70541 WDP4 D/IZN from loco yard line no. 3 to line no. 4 working DSL loco no. 40496 WDP4 D/SPJ/derailed by 6 wheel of HWH trolley due to 2-route of Hand Point no. L-3 at 19.55 hrs. Cause: Two route of hand point no. L-3.
3	26.05.18	Sr. Sub. D-6	Derailment(ALD Yard) - While shunting from troop siding to Line no. 15 wagon no. 58241610946 M 8055 BOM N derailed by all wheel near Point no. 398A,

		PRYJ	movement in Illrd line SFG-ALD held up. UP & DN main line clear. Cause:- Wagon & track defect.
4	01.06.18	Sr. Sub. D-6 PRYJ	Derailment (Aligarh Yard)- Train UP ALJN Spl. loaded with Cement was placed in CD siding for unloading. During unloading Cement from wagon no. 33111093751 NWR BCNHL toppled in south side from outside of the track. Cause:- Due to uneven loading of cement by the private laborers.
5	06.06.18	Sr. Sub. B-7 AGC	Fire(Agra Yard)- Three coaches stabled in shuttle line no. 2 for disposal since 19.03.18, coach no. NC 92473 GSDMU caught fire. Cause:- Due to miscreant activity.
6	06.08.18	Sr. Sub. D-6 PRYJ	Derailment (ICD/DERyd.)- While taking out load from ICD/DER siding to L.N. 10, derailment of wagon no-62259960153 BLC B/CONCOR on point no-243 at DER Yard. Cause:- Due to Poor track maintenance and container loading not in proper way.
7	12.08.18	JAG D-6 PRYJ	Derailment (GMC Yd.)- While movement of coupled L/Engine for L. N. 15 to DSL trip shed, CNB two wheels of AGC end Axle no. 6 of dead loco 40166 WDP4D/ET derailed at Diamond Crossing of point no. 353. Cause:- Due to poor maintenance of loco by Home shed Itarsi.
8	17.08.18	Sr. Sub. D-6 PRYJ	Derailment (ACOI Yd.)- Train No. NYN Goods Shunt backed from L. N. 15 wrongly on signal given to L.N. 14 by shunting staff resulting in derailment of BV-85028911071 ER by all wheels & wagon no. 30019562749 R by all wheels of DLI end trolley on open trap point no. 255-A at 00.30. Cause:- Due to Carelessness of shunting staff.
9	18.08.18	Sr. Sub. D-6 JHS	Derailment (PIC Yd.)- Derailed of two wagons of train no. E/BOXN at PIC Yard. Cause:- Due to Twist in track found beyond permissible limit.
10	19.08.18	Sr. Sub. D-6 JHS	Derailment (PIC Yd.)- Derailed of two wagons of train no. E/BOXN at PIC Yard. Cause:- Due to Twist in track found beyond permissible limit.
11	29.08.18	Sr. Sub. D-6 PRYJ	Derailment (Chunar Yd.)- Derailed of Brake van & wagon of LRD goods in Line no. 7 at CAR Yard. Cause:- Due to Uneven loading & excessive twist in the track.
12	01.09.18	Sr. Sub. D-6 JHS	Derailment (Gwalior Yd.)- Derailed of two DBKM/E wagons at Gwalior yard. Cause:- Due to poor maintenance of track.
13	06.09.18	Jr. Scale D-6 PRYJ	Derailment (Harduaganj Yd.)- While placement of rake by pushing back in line no. 12 Clinker siding BV No. ECR BV 2186101267566 derailed by all wheels of AUR end trolley in line 12. Cause:- Due to infringement with old sleeper near the track.
14	10.09.18	Sr. Sub. D-6 PRYJ	Derailment (Subedarganj Yd.)- Derailed at SFG Yard of 2 BOBYN empty wagons of DMT. While shunting from IOC siding to line no. 8 of SFG Yard, 8 th & 9 th wagons from EP derailed. Cause:- Due to uneven unloading in wagon.
15	01.11.18	Jr. Scale R-5 PRYJ	Misc. (Kailhat Yd.)- While unloading sleepers from DMT in UP loop line, three railway engineering staff and three private laborer injured with OHE wire at 10.35 hrs. Cause:- Slack supervision by the engineering staff.
16	04.11.18	JAG B-7 JHS	Fire (Jhansi Yd.)- Fire in one coach no.05247 NR in JHS yard. Cause:- Due to smoking of Bidi by person.
17	07.12.18	Sr. Scale D-6 PRYJ	Derailment (GMC Yd.)- Derailed of Diesel power No. 1352/WDG3A/KTE by DLI end trolley 6 wheels during shunting on open trap point No.431A. Cause:- Due to overlook of shunt signal no. 245 by Shunter.

18	22.12.18	Sr. Sub. D-6 JHS	Derailment (Burhpura station) -Derailment of one wagon first from engine of train no. E/BOXN Goods. Cause:- Dashed while attaching engine on stable load in UP loop line by Loco Pilot.
19	05.03.19	Sr. Scale D-6 PRYJ	Derailment (CPC Yd) -Derailment of 2 wagons of BCN/E at CPC yard on H.P. No. 3. Cause:- Negligence of shunting staff.
20	06.03.19	Sr. Scale D-6 PRYJ	Derailment (Churk station) -Derailment of 1 wagon of HIMB Spl. in CUK station. Cause:- Versine variation and tight gauge of the track.
21	19.03.19	Jr. Scale D-5 PRYJ	Derailment (Mirzapur station) -Derailment of T/Wagon on open trap point no. 210 a at MZP yard. Cause: Driver of T/wagon over look the shunt signal no. 126.
22	28.03.19	Sr. Sub. D-6 PRYJ	Derailment (Allahabad station) -Derailment of 01 VPU coach during shunting from coaching yard to OC siding. Cause: Excess pushing due to negligence of shunting staff.
Unusual: (02)			
1	05.08.18	JAG R-5 PRYJ	Unusual (PANKI) -While unloading Iron broom in line no. 14 of PNK Yard, derailment of BOXNHL 22141226484 SECR of train no. DN PNK. Cause:- due to Uneven unloading by private party KL Steel.
2	11.11.18	Sr. Sub. D-6 JHS	Derailment (Khajuraho Yd.) - Loco no.14872 was to be shunted in ART line and to be load on RDSO/SPL but while passing HP No.2 loco was derailed. Cause:- Due to improper clamping of point no. HP-2.
Equipment failure: (01)			
1	05.05.18	SAG J-1 JHS	Fire - Heavy smoke in loco no. 16810 WDM3A/ABR of train no. 19665 Khajuraho – Udaipur city Intercity Exp. between BelaTal–Harpalpursection. Cause:- Inter cooler of compressor red hot due to high temperature.