

RMS LOCATIONS OVER NCR		
DIVISION	Location	Nos.
AGRA	AGRA Control office	5
	BAAD	2
JHS	Jhansi Control office	4
	BAB Station	1
	VGLJ	1
PRYJ	PRYJ Control office	7
	GMC Control office	7
	TDL Control office	5

COA LOCATIONS OVER NCR		
S.No	Location	Nos.
1	PRYJ Control office	20
2	TDL Control office	20
3	AGRA Control office	25
4	JHANSI Control office	30