

Details of Train Accidents 2017-18

A. Details of Consequential Train Accidents

1	23.08.17	CRS	Derailment (Pata-Achhalda): Dashing of dumper with train no. 12225 between Pata-Achhalda Station of ALD Division. (0 Killed, 19 Grievous, 30 Simple Injury). Cause: Error in working near track-negligence of road Dumper driver and DFCCIL administration.
		PRYJ	
2	24.11.17	CRS	Derailment (Manikpur): Derailment of 14 coaches of Train No. 12741 at Manikpur station of ALD Division. (04 Killed, 05 Grievous, 03 Simple injury). Preliminary report received on 29.12.17. Action taken report is sent on 07.02.2018 to Railway Board. Cause:- Rail fracture.
		PRYJ	
3	20.01.18	SAG	Derailment (Farah-Kitham): Derailment of one VPH of train no. 12410 in between FAR-KXM section. Cause:- Due to CRO.
		AGC	
4	03.05.17	JAG C-3	UMLC (Patara – Ghatampur)- Tractor Trolley dashed with train no. 51802 at UMLC No. S-65 between Patara – Ghatampur of JHS Division. Cause:- Negligence of road user driver.(02 outsider Killed)
		JHS	
5	03.05.17	JAG C-3	UMLC (Gohad – Sanichara)- TATA Magic dashed with train no. 59825 at UMLC No. 35/C between Gohad – Sanichara of JHS Division. Cause:- Negligence of road user driver. (04 Killed, 01 Grievous outsider)
		JHS	

B. Details of Consequential Train Accidents

Indicative: (02)			
1	05.04.17	Sr. Scale	BOBR- Traffic block was enforced from 16.05 to 17.05 hrs between JJK-AAP for SEJ gap adjustment. SM/JJK made through departure signal for train no. 12398 Mahabodhi Exp. Cause:- Negligence of On duty ASM/JJK.
2	22.01.18	JAG	SPAD- Loco Pilot of train no. 12493 passed Intermediate Starter Signal no. 14 at danger position at MTJ. Cause:- Negligence of LP/ALP. (Crew – WCR) (Distance crossed -198 meter)
Other Train Accident : (02)			
3	04.10.17	Sr. Sub.	Derailment of three wagons of MLJ Spl. while entering in L.N.5 at MTJ Yard. Cause:- Due to poor maintenance of wagon by RYPS Workshop/SC Rly.
4	22.06.17	JAG	Derailment –CP Spl. Goods derailed between FAB-HAB station at km no. 1377/396 at 08:58 hrs consequently 3 wagons and B/van derailed. Cause:- Due to sinking of track of LHS 18 on approach.
Yard derailment: (08)			
1	20.04.17	Sr. Supervisor	Derailment of Empty wagon EcoR 63452 at COI yard during shunting. Cause: Due to poor track condition of TSL siding and poor maintenance of wagon by C&W department.
2	15.07.17	Sr.Scale	Derailment (Tundla Yd.): Derailment of one coach of train no. 54467 at TDL Yard during shunting. Cause:- Due to deviations in standard values of track parameters and reverse cant on the curve.
3	04.08.17	JAG	Fire(Gwalior Yd.): E/Rake of train no 11112, fire on coach no. NC14401 GS, fire brigade arrived at 19.05 hrs, work started at 19.12 hrs and fire extinguished at 19.54 hrs. Cause:- Proper locking of doors was not ensured by on duty C&W supervisor through contractor staff.

4	22.08.17	Sr. Sub.	Derailment (Allahabad Yd.): Derailment of L/Engine No. 22266 WAP-4/CNB derailed by Delhi end six wheels at HP no T-60. Cause:- Due to carelessness of shunting staff. no route.
5	25.01.18	Sr. Sub.	Fire (Mathura Yd.): Fire in coach No.07535 GS of train No.55340 Up Empty rake, Caught fire in PF N. 09 at Mathura Yard. Cause:- Due to short circuit.
6	08.02.18	Sr. Sub.	Derailment (Orai Yd.): Derailment of two empty BCNHL No. ECR 33101112907 & ECOR 33121189033 at new goods siding Orai yard. Cause:- Due to infringement of wheat bags with the track.
7	19.02.18	Sr. Sub.	Derailment (ALD Yd.): Derailment of 3 military coaches and 01 wagon during shunting from line no 23 to 16 at ALD Yd. Cause:- Due to defect in track and wheel trolley of wagon.
8	06.03.18	Sr. Sub.	Derailment (ALD Yd.): Derailment of one E/coach during shunting from sick line to line no 23 at ALD Yd. Cause:- Not proper setting of hand point no. T-4. Responsibility: shunting staff.
Unusual: (01)			
1	04.04.17	Jr. Scale	Unusual- Five passenger of train no. 64588 got injury while travelling on door/ foot step on coach no. 30050 between BNT-SHW stations due to door of UP Goods train no. MJ-5 detached from wagon and hit the foot step of coaches of Dn MEMU train no. 64588. Cause:- Carelessness of the passenger.