

## Details of Accident over NCR during the year 2022-23

## Annexure-C

SN	Date	Category / Div.	Brief Particular	Enquiry level	Enquiry completion (days) D+10	Cause	Responsibility	Action Taken
<b>A Consequential Train Accidents (1)</b>								
1	04.10.22	D-3 PRYJ	Derailment of four wheels of rear trolley of 3rd coach of train no. DN 18102 Muri Exp. due to CRO (heavy bull) at Km no. 1389/2 between Starter and Advance Starter Signal of Wair Station at 08.25 hrs.	JAG		CRO		
<b>B Non-Consequential Train Accidents (7)</b>								
<b>a Indicative Accidents (2)</b>								
1	04.05.22	H-2 JHS	LP of train no. DN JAB Goods (EP no. 33124), passed the DN Starter signal and Adv. Starter Signal in ON position at Lalitpur Yard.	JAG	10	Erratic behavior of the formation at the time of SPAD & late application of brake by Loco Pilot.	Primary: - 1. Erratic behavior of the formation at the time of SPAD at LAR. Secondary- 1. Sh Amit Kr Sharma, LPG/VGLB 2. Sh. Ashok Kr Kushwaha, ALP/VGLB	Primary: - Inquiry report sent to Sr. DME/C&W on 18.05.22 Secondary- 1. Reduction to lower stage for 05 Years with CE. 2. Reduction to lower stage for 05 Years with CE.
2	17.08.22	H-1 AGC	LP of train no. UP 12156 Exp. (EP no. 30735/AQ/CR) passed up starter signal no. S-3 in ON position at Raja Ki Mandi at 22.47 hrs.	JAG	06	LP and ALP of 12156 failed to observe the UP Starter signal S-3 of RKM station in danger position.	Primary:- 1. Sh. A.K. Mahajan /LPM/JHS 2. Sh. Harphool Meena/Sr.ALP/JHS Secondary- 1. Sh V.K.Kanojiya/CLI/JHS 2. Sh Firdos Khan /CLI/JHS	Primary:- 1. SF-5 issued On 22.08.22 2. SF-5 issued On 22.08.22 Secondary- 1. WIT two year without CE . 2. WIT two year without CE
<b>b Other Train Accidents (1)</b>								
1	05.08.22	D-5 PRYJ	DLI end axle of HWH end trolley, 20th wagon from EP derailed due to door of 18th wagon from engine rubbed with PF and entangled at Km no. 906/20 of train no. DN KM 16 Goods at Khaga Yard.	Sr./Jr. Scale	07	Wheel of derailed wagon (20th) entangled with broken door of 18th wagon.	Primary:- 1. CGS(Consignee)/PMKM/NR. 2. Optg. Dept./DLI/NR. 3. LP&Guard(GDR)/DLI/NR Secondary- 1. Sh.Sunil Kumar Bhartiya/ALP (working as Guard)/PRYJ 2. Sh.Neeraj/Poinsman/Khaga/PRYJ 3. K.C. Panday/CLI/PRYJ 4. Sh. Nitish Kumar/Dy.Op./TDL 5. Sh. Girish Upadhyay/TI/KGA 6. All joint signatories.	Secondary- 1. Warning. 2. Counseling. 3. Warning. 4. Counseling. 5. Counseling.

## Details of Accident over NCR during the year 2022-23

SN	Date	Category / Div.	Brief Particular	Enquiry level	Enquiry completion (days) D+10	Cause	Responsibility	Action Taken
<b>c Yard Accidents (2)</b>								
1	22.05.22	D-6 JHS	Derailment of six wheels of bogie no. 2 of EP no. 31712 at point no. 113 in Antri yard on dated 22.05.22 at 09.17 hrs.	Jr. scale	03	Proper securing of dead loco was not ensured by LP,ALP of loco no.31841 (working loco).	Primary: - 1. Sh. suresh kumar/LPG/VGLB 2. Sh. Kamlesh singh/ALP/VGLB 3. Sh. Asid khan/ALP/VGLB Secondary- 1.Sh. Vipin kumar/P-Man/ARI	Primary: - 1. WIT two year without CE 2. WIT two year without CE 3. WIT two year without CE Secondary- 1. WH 2 set prev. pass.
2	24.07.22	D-6 AGC	Derailment of 4 wheels leading trolley of empty Coach no. BRC 20074 of train no. 19109 EMU Rake near Point no. 24 in Goods line no.1 at 0.55 hrs at Mathura Yard.	Jr. scale	10	The Shunting Supervisor and Pointsman did not ensure the correct setting and locking of point during shunting.	Primary: - 1.Sh. Rakesh Sonwal/Gd/Kota/WCR 2.Sh. Krishna/Pointsman/MTJ Secondary- 1.Sh. Girraj Singh/Black Smith/MTJ 2.Sh. Kanwar Singh/Signal Maintainer-II/MTJ	Primary: - 2. SF-11 issued on 29.08.22 Secondary- 1. SF-11 issued on 25.08.22 2. SF-11 issued on 25.08.22
<b>d Equipment Failure/Unusual (2)</b>								
1	09.05.22	R-5 PRYJ	Train no. 22450 DN (NDLS-GHY) Exp. slightly rubbed with tractor no. UP 70V 2490 with trolley between km no. 1103/2 - 1102/28 in Pata – Phaphund Block Section.	Sr. sub.	03	Negligence of tractor driver.	Primary:- 1. Outsider. 2. Sri Ashok Kumar II/LP/TDL 3. Sri Mahendra Meena/ALP/TDL 4. Sri Saroj Kumar/Guard/TDL (of T.no. 13484 Exp.) Secondary- 1.Sri MukeshYogi/TM-1Mate/PHD 2. Sri Naman Pandey/Tech-II/CNB 3.Sri Govind Maurya/Tech-III/CNB 4.Sri Ram Naresh singh/Tech-II/CNB	Primary: - 2. WIT two year without CE 3. WIT two year without CE 4.WH prev. pass & PTO. Secondary- 1. WH prev. pass & PTO 2. WH prev. pass.& PTO 3. WH prev. pass.& PTO 4. WH increment without CE
2	06.09.22	K-7 JHS	Guard of train no. DN 12269 Exp. reported that ACP done by ETL Staff at KM 1021/34 between JLN-JRO as junction box broken and rail piece entangled with Pantry Car no. SR-195464. Also BP Pipe of sleeper coach no. SR -203754 broken.	JAG	03	The check rail was in damaged condition and its bolts were missing and there was pumping action on running rail.	Primary: - 1. Sh.Sunny Verma/PWI/DUA Blameworthy:- 1. Sh. Hanuman Das/SM/DUA 2. Sh. Alok Sahu/Gateman/Optg./DUA	Primary: - 1. SF-5 issued on 13.09.22. Blameworthy:- 1. Warning 2. Warning