

Passenger Amenities Details As on : 31/03/2021

Division : Jhansi

| | | | | | | | | | |
|-----------------------------|---|------------------------------|---|--|------------------------------|---------|----------------------------|------------------------------------|-------|
| Station Name | Bhadroli | | | No. of passengers dealt with: | | | | Identified as Adarsh | N |
| Station Code | BBY | FOB | 0 | (a) Per Day | | 0 | Developed As Adarsh | | |
| Station Category | HG3 | Subway | 0 | (b) Max. at any time | | 0 | Identified for MFC | | |
| Railway | NCR | Booking Windows | 1 | Pass. Earnings/Year(Rs. in Lac.) | | | | | |
| Division | Jhansi | Enquiry Office | 0 | 2011-12 | 1.00 | 2016-17 | 1.60 | Tourist Facilation Center | |
| State | MADHYA | Public Address Sys. | N | 2017-18 | 0 | 2018-19 | 0.01 | Touch Screen Enquiry System | |
| District | PRADESH GWALIOR | Clock | N | 2019-20 | 1.1 | 2020-21 | 0 | Electronic Train Indication | |
| Section | GWL-BIX | Wheel Chairs | N | Length of longest stopping train(m) | | | 280 | ATMs | |
| Km. | 1235.465 | Cloak Room | N | MP Const. | Gwalior | | | Food Plaza | |
| Route | E | Refreshment Room(sqm) | | MP Name | Sri Vivek Narayan Shejwalkar | | | Budget Hotel | |
| Electrified | N | | | MLA Const. | Gwalior | | | Trains Halting | |
| Other Items | Nil | | | MLA Name | Sh. Pradyuman Singh Tomar | | | M: 0 | P : 6 |
| Remarks for Station: | Station building is satisfactory. Exemption granted by GM/NCR for clock, dt 02.06.2017. Sr.DEE(G)- Exempted for Electrification as per HQ/ALD L.N. Elect./PS/NCR/Power dated 16.07.18 | | | | | | | | |

Resting Facility

| WAITING HALL | | WAITING ROOM | | GENTS | LADIES | UPPER CLASS WAITING ROOM | | | |
|----------------------------|----|------------------------|--|-------|--------|--------------------------|---|----------------------|---|
| (a) Area(sqm.) | 10 | Area(sqm) | | 0 | 0 | Area(sqm) | 0 | Retiring Room | 0 |
| (b) Seats(Nos.) | 4 | Seats(Nos.) | | 0 | 0 | Seats(Nos.) | 0 | Dormitory | 0 |
| (c) Lav.(Nos.) | 0 | Lav.(Nos.) | | 0 | 0 | Lav.(Nos.) | 0 | | |
| (d) Urinals(Nos.) | 0 | Urinals(Nos.) | | 0 | 0 | Urinals(Nos.) | 0 | | |
| (e) Bathing Cubicals(Nos.) | 0 | Bathing Cubicals(Nos.) | | 0 | 0 | Bathing Cubicals(Nos.) | 0 | | |

Circulating Area and Water Supply

| Circulating Area | | Approach Road | | Water Supply | | | |
|-----------------------------|---------------|--------------------------|---------|------------------------------|----------------------------------|-------------------------|---|
| Area (sqm) | 0 | Length(m) | 700 | Source | Railway Supply | Open Wells (Nos) | 0 |
| Surface | Kutchra | Surface | Kutchra | Type | Hand Pump | Bore Wells (Nos) | 0 |
| Illumination Type | Normal Lights | Illumination Type | N | Storage Capacity(Ltr) | 0 | | |
| Pay & Use Toilet | | | | Remarks | Benches are in broken condition. | | |

Station Name : Bhadroli

Platform Detail

| PF No. | Gauge | Island PF | Length (m.) | Breadth (m.) | Height (cm.) | Surface* | Shelter sq.m. | Trees Nos. | Taps Nos. | Hand Pumps Nos. | Washable Apron(m.) | Carr. Watering (m.) | Seats Nos. | Lav. Nos. | Urinals Nos. | Fans Nos. | Lights Nos. | Vending Stall Nos. | CC-TV Nos. | Lift Nos. | Escalator Nos. | FOBs (No.) on PF | Coach Indication Board | Ramp along FOB(No.) | |
|---------------|-------|----------------------|-------------|--------------|-------------------|----------|---------------|-------------------------|-----------|-----------------|--------------------|---------------------|------------|------------|--------------|-----------|-------------|--------------------|------------|-----------|----------------|------------------|------------------------|---------------------|---|
| 1 | BG | N | 132 | 6 | 0 | OTH | 0 | 8 | 0 | 1 | | 0 | 18 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | N | 0 |
| *Surface Type | | : CC-Cement Concrete | | | PS-Polished Stone | | | OPS-Other Pucca Surface | | | MOR-Moorum | | | OTH-Others | | | | | | | | | | | |

Station Name : Bhadroli

Summary

(As per Railway Board's Letter No. 2012/LM (PA)/3/5 Dt. 11.09.2012)

| Item -> | Waiting Hall (sqm) | Shelter (sqm) | TAP/HP (nos) | Lavatories (nos) | Urinals (nos) | Seats (nos) | FOB (nos) | Height of Platforms | No of Water Coolers | Signage |
|-------------------|--------------------|---------------|--------------|------------------|---------------|-------------|-----------|----------------------|---------------------|---------|
| Min. Facility | 0 | Shady Trees | 1 HP at stn | 0 | 0 | 0 | 1 | High level | 0 | - |
| As per Rec. norms | 0 | 0 | 0 | 0 | 0 | 0 | | | - | - |
| Actual | 10 | 0 | 1 | 1 | 0 | 22 | 0 | See platform details | 0 | - |
| Shortage, if any | - | - | - | - | - | - | 1 | | - | - |