

Passenger Amenities Details As on : 31/03/2021

Division : Jhansi

<b>Station Name</b>	<b>Jiron</b>			<b>No. of passengers dealt with:</b>				<b>Identified as Adarsh</b>	<b>N</b>
<b>Station Code</b>	<b>JRO</b>	<b>FOB</b>	<b>0</b>	<b>(a) Per Day</b>		<b>0</b>		<b>Developed As Adarsh</b>	
<b>Station Category</b>	<b>NSG6</b>	<b>Subway</b>	<b>0</b>	<b>(b) Max. at any time</b>		<b>0</b>		<b>Identified for MFC</b>	<b>N</b>
<b>Railway</b>	<b>NCR</b>	<b>Booking Windows</b>	<b>1</b>	<b>Pass. Earnings/Year(Rs. in Lac.)</b>					
<b>Division</b>	<b>Jhansi</b>	<b>Enquiry Office</b>	<b>0</b>	<b>2011-12</b>	<b>2.00</b>	<b>2016-17</b>	<b>1.70</b>	<b>Tourist Facilation Center</b>	<b>N</b>
<b>State</b>	<b>UTTAR</b>	<b>Public Address Sys.</b>	<b>Y</b>	<b>2017-18</b>	<b>1.26</b>	<b>2018-19</b>	<b>0.73</b>	<b>Touch Screen Enquiry System</b>	<b>N</b>
<b>District</b>	<b>PRADESH LALITPUR</b>	<b>Clock</b>	<b>Y</b>	<b>2019-20</b>	<b>0.73</b>	<b>2020-21</b>	<b>0</b>	<b>Electronic Train Indication</b>	<b>N</b>
<b>Section</b>	<b>BIN-AGC</b>	<b>Wheel Chairs</b>	<b>Y</b>	<b>Length of longest stopping train(m)</b>			<b>230</b>	<b>ATMs</b>	<b>0</b>
<b>Km.</b>	<b>1028.25</b>	<b>Cloak Room</b>	<b>N</b>	<b>MP Const.</b>	<b>Jhansi</b>			<b>Food Plaza</b>	<b>N</b>
<b>Route</b>	<b>A</b>	<b>Refreshment Room(sqm)</b>		<b>MP Name</b>	<b>Shri Anurag Sharma</b>			<b>Budget Hotel</b>	<b>N</b>
<b>Electrified</b>	<b>Y</b>			<b>MLA Const.</b>	<b>Lalitpur</b>			<b>Trains Halting</b>	<b>M: 0 P : 4</b>
				<b>MLA Name</b>	<b>Shri Ramratan Kushwaha</b>			<b>Station IInd Entry</b>	<b>N</b>
<b>Other Items</b>	<b>Nil</b>								
<b>Remarks for Station:</b>	Station building is satisfactory. Relaxation in no. of Booking counter as per Dy.CE P&D vide letter No.264-W/NCR/ALD/Pt-IX/Genl. dated 22-01-16. Sr.DEE(G)-Exempted for fan by HQ/ALD on 08.08.2019.								

Resting Facility

WAITING HALL		WAITING ROOM		GENTS	LADIES	UPPER CLASS WAITING ROOM			
(a) Area(sqm.)	33	Area(sqm)		0	0	Area(sqm)	0	Retiring Room	0
(b) Seats(Nos.)	12	Seats(Nos.)		0	0	Seats(Nos.)	0	Dormitory	0
(c) Lav.(Nos.)	0	Lav.(Nos.)		0	0	Lav.(Nos.)	0		
(d) Urinals(Nos.)	0	Urinals(Nos.)		0	0	Urinals(Nos.)	0		
(e) Bathing Cubicals(Nos.)	0	Bathing Cubicals(Nos.)		0	0	Bathing Cubicals(Nos.)	0		

Circulating Area and Water Supply

Circulating Area		Approach Road		Water Supply				
Area (sqm)	98	Length(m)	0	Source	Railway Supply		Open Wells (Nos)	1
Surface	Cement Concrete	Surface	Other	Type	Hand Pump		Bore Wells (Nos)	0
Illumination Type	Normal Lights	Illumination Type	N	Storage Capacity(Ltr)	0			
Pay & Use Toilet				Remarks	Water supply is satisfactory, No water arrangement in toilet.			

Station Name : Jiron

Platform Detail

PF No.	Gauge	Island PF	Length (m.)	Breadth (m.)	Height (cm.)	Surface*	Shelter sq.m.	Trees Nos.	Taps Nos.	Hand Pumps Nos.	Washable Apron(m.)	Carr. Watering (m.)	Seats Nos.	Lav. Nos.	Urinals Nos.	Fans Nos.	Lights Nos.	Vending Stall Nos.	CC-TV Nos.	Lift Nos.	Escalator Nos.	FOBs (No.) on PF	Coach Indication Board	Ramp along FOB(No.)	
1	BG	N	351	9	0	OPS	72	12	0	2		0	33	2	1	0	6	0	0	0	0	0	N	0	
2 & 3	BG	Y	351	9	0	OTH	72	28	0	2		0	21	0	0	0	1	0	0	0	0	0	N	0	
*Surface Type : CC-Cement Concrete PS-Polished Stone OPS-Other Pucca Surface MOR-Moorum OTH-Others																									

Station Name : Jiron

Summary

(As per Railway Board's Letter No. 2012/LM (PA)/3/5) Dt. 11.09.2012)

Item ->	Waiting Hall (sqm)	Shelter (sqm)	TAP/HP (nos)	Lavatories (nos)	Urinals (nos)	Seats (nos)	FOB (nos)	Height of Platforms	No of Water Coolers	Signage
Min. Facility	15	100 sqm	4 tap/HP at stn	1	1	20	1	High level	0	-
As per Rec. norms	0	0	0	0	0	0			-	-
Actual	33	144	4	2	1	66	0	See platform details	0	-
Shortage, if any	-	-	-	-	-	-	1		-	-