

Passenger Amenities Details As on : 31/03/2021

Division : Jhansi

Station Name	Orai			No. of passengers dealt with:				Identified as Adarsh	Y
Station Code	ORAI	FOB	1	(a) Per Day	514		Developed As Adarsh	Y	
Station Category	NSG4	Subway	0	(b) Max. at any time	52		Identified for MFC	Y	
Railway	NCR	Booking Windows	3	Pass. Earnings/Year(Rs. in Lac.)				MFC Developed	N
Division	Jhansi	Enquiry Office	1	2011-12	941.00	2016-17	1212.91	Tourist Facilitation Center	N
State	UTTAR	Public Address Sys.	Y	2017-18	278.15	2018-19	1142.77	Touch Screen Enquiry System	Y
District	PRADESH JALAUN	Clock	Y	2019-20	1080.75	2020-21	230.11	Electronic Train Indication	Y
Section	JHS-CNB	Wheel Chairs	Y	Length of longest stopping train(m)				ATMs	1
Km.	1241.47	Cloak Room	N	600				Food Plaza	N
Route	D	Refreshment Room(sqm)	45	MP Const.	Jalaun			Budget Hotel	N
Electrified	Y			MP Name	Bhanu Pratap Singh Verma			Trains Halting	M: 32 P : 4
				MLA Const.	Orai			Station IInd Entry	N
				MLA Name	Shri Gauri Shankar				
Other Items	Nil								
Remarks for Station:	Station building is satisfactory. Relaxation in no. of Booking counter as per Dy.CE P&D vide letter No.264-W/NCR/ALD/Pt-IX/Genl. dated 22-01-16. Relaxation in STD/PCO booth has been granted by GM/NCR as per Sr. DCM letter no.- C/160/MEA/PA, dt 15.05.2017.								

Resting Facility

WAITING HALL		WAITING ROOM		GENTS	LADIES	UPPER CLASS WAITING ROOM			
(a) Area(sqm.)	270	Area(sqm)		73	0	Area(sqm)	0	Retiring Room	1
(b) Seats(Nos.)	56	Seats(Nos.)		18	0	Seats(Nos.)	0	Dormitory	0
(c) Lav.(Nos.)	0	Lav.(Nos.)		2	2	Lav.(Nos.)	0		
(d) Urinals(Nos.)	0	Urinals(Nos.)		1	1	Urinals(Nos.)	0		
(e) Bathing Cubicals(Nos.)	0	Bathing Cubicals(Nos.)		1	1	Bathing Cubicals(Nos.)	0		

Circulating Area and Water Supply

Circulating Area		Approach Road		Water Supply				
Area (sqm)	4156	Length(m)	500	Source	Railway Supply		Open Wells (Nos)	1
Surface	Black Topped	Surface	Black Topped	Type	Piped		Bore Wells (Nos)	1
Illumination Type	Normal Lights	Illumination Type	Y	Storage Capacity(Ltr)	225000			
Pay & Use Toilet				Remarks	Water supply is adequate.Water cooler out of order.			

Station Name : Orai

Platform Detail

PF No.	Gauge	Island PF	Length (m.)	Breadth (m.)	Height (cm.)	Surface*	Shelter sq.m.	Trees Nos.	Taps Nos.	Hand Pumps Nos.	Washable Apron(m.)	Carr. Watering (m.)	Seats Nos.	Lav. Nos.	Urinals Nos.	Fans Nos.	Lights Nos.	Vending Stall Nos.	CC-TV Nos.	Lift Nos.	Escalator Nos.	FOBs (No.) on PF	Coach Indication Board	Ramp along FOB(No.)
1	BG	N	620	7.5	84	OPS	911	12	31	0		0	191	7	4	18	55	1	0	0	0	1	Y	0
2/3	BG	Y	543	6	84	OPS	542	0	22	0		0	103	0	4	10	39	0	0	0	0	1	Y	0

*Surface Type : CC-Cement Concrete PS-Polished Stone OPS-Other Pucca Surface MOR-Moorum OTH-Others

Station Name : Orai

Summary

(As per Railway Board's Letter No. 2012/LM (PA)/3/5) Dt. 11.09.2012)

Item ->	Waiting Hall (sqm)	Shelter (sqm)	TAP/HP (nos)	Lavatories (nos)	Urinals (nos)	Seats (nos)	FOB (nos)	Height of Platforms	No of Water Coolers	Signage
Min. Facility	75	400 sqm	40	6	6	200	1	High level	4	YES
As per Rec. norms	22	29	2.08	0	0	6			-	-
Actual	270	1452	54	11	10	368	1	See platform details	4	YES
Shortage, if any	-	-	-	-	-	-	-		-	-

Station Name : Orai

Summary As per Modern Station

Desired Facility	Facility Available
Improvement in the facade of the station building	Yes
Improvement in the circulating area so as to ensure proper entry and exit of	Yes
A lighting tower at an appropriate place to be installed for proper illumination	Yes
Improved modern, cost effective lighting arrangements at the platforms,	Yes
Renovated water booths	Yes
Renovated, modern, Pay & Use toilets	Yes
Good Waiting and Retiring Rooms with modern furniture	Yes
Good passenger guidance system including signages and coach indication	Yes
Improvement to the passenger service	Yes
Improvement of booking and enquiry offices to give them a facelift	Yes
Lighting of booking offices, the queuing area in front of booking windows	Yes
Engagement of reputed architects/consultants for beautification	Yes