

Passenger Amenities Details As on : 31/03/2021

Division : Jhansi

| | | | | | | | | | |
|-----------------------------|---|-------------------------------|---|--|-------------------------|---------|--------|------------------------------------|------------|
| Station Name | Ragaul | | | No. of passengers dealt with: | | | | Identified as Adarsh | N |
| Station Code | RGU | FOB | 1 | (a) Per Day | | 132 | | Developed As Adarsh | |
| Station Category | NSG5 | Subway | 0 | (b) Max. at any time | | 33 | | Identified for MFC | N |
| Railway | NCR | Booking Windows | 1 | Pass. Earnings/Year(Rs. in Lac.) | | | | | |
| Division | Jhansi | Enquiry Office | 0 | 2011-12 | 209.00 | 2016-17 | 285.36 | Tourist Facilation Center | N |
| State | UTTAR | Public Address Sys. | Y | 2017-18 | 286.36 | 2018-19 | 230.19 | Touch Screen Enquiry System | N |
| District | PRADESH HAMIRPUR | Clock | Y | 2019-20 | 227.53 | 2020-21 | 42.22 | Electronic Train Indication | N |
| Section | BNDA-CNB | Wheel Chairs | Y | Length of longest stopping train(m) | | | 310 | ATMs | 0 |
| Km. | 1338.16 | Cloak Room | N | MP Const. | Hamirpur | | | Food Plaza | N |
| Route | D | Refreshment Room(sq.m) | | MP Name | Kunwar Pushpendra Singh | | | Budget Hotel | N |
| Electrified | N | | | MLA Const. | Hamirpur | | | Trains Halting | M: 6 P : 4 |
| | | | | MLA Name | Shri Yuvraj Singh | | | Station IInd Entry | N |
| Other Items | Nil | | | | | | | | |
| Remarks for Station: | Station building is satisfactory. Relaxation in no. of Booking counter as per Dy.CE P&D vide letter No.264-W/NCR/ALD/Pt-IX/Genl. dated 22-01-16. | | | | | | | | |

Resting Facility

| WAITING HALL | | WAITING ROOM | | GENTS | LADIES | UPPER CLASS WAITING ROOM | | | |
|----------------------------|----|------------------------|--|-------|--------|--------------------------|---|----------------------|---|
| (a) Area(sq.m.) | 44 | Area(sq.m) | | 0 | 0 | Area(sq.m) | 0 | Retiring Room | 0 |
| (b) Seats(Nos.) | 8 | Seats(Nos.) | | 0 | 0 | Seats(Nos.) | 0 | Dormitory | 0 |
| (c) Lav.(Nos.) | 0 | Lav.(Nos.) | | 0 | 0 | Lav.(Nos.) | 0 | | |
| (d) Urinals(Nos.) | 0 | Urinals(Nos.) | | 0 | 0 | Urinals(Nos.) | 0 | | |
| (e) Bathing Cubicals(Nos.) | 0 | Bathing Cubicals(Nos.) | | 0 | 0 | Bathing Cubicals(Nos.) | 0 | | |

Circulating Area and Water Supply

| Circulating Area | | Approach Road | | Water Supply | | | | |
|-----------------------------|---------------|--------------------------|--------------|------------------------------|---|--|-------------------------|---|
| Area (sqm) | 2450 | Length(m) | 15 | Source | Railway Supply | | Open Wells (Nos) | 1 |
| Surface | Black Topped | Surface | Black Topped | Type | Piped | | Bore Wells (Nos) | 1 |
| Illumination Type | Normal Lights | Illumination Type | N | Storage Capacity(Ltr) | 1000 | | | |
| Pay & Use Toilet | | | | Remarks | Water supply is adequate &One RCC(OH)tank Cap 50 kilo | | | |

Station Name : Ragaul

Platform Detail

| PF No. | Gauge | Island PF | Length (m.) | Breadth (m.) | Height (cm.) | Surface* | Shelter sq.m. | Trees Nos. | Taps Nos. | Hand Pumps Nos. | Washable Apron(m.) | Carr. Watering (m.) | Seats Nos. | Lav. Nos. | Urinals Nos. | Fans Nos. | Lights Nos. | Vending Stall Nos. | CC-TV Nos. | Lift Nos. | Escalator Nos. | FOBs (No.) on PF | Coach Indication Board | Ramp along FOB(No.) |
|--------|-------|-----------|-------------|--------------|--------------|----------|---------------|------------|-----------|-----------------|--------------------|---------------------|------------|-----------|--------------|-----------|-------------|--------------------|------------|-----------|----------------|------------------|------------------------|---------------------|
| 1 | BG | N | 575 | 10 | 84 | CC | 935 | 0 | 14 | 1 | | 0 | 104 | 4 | 4 | 5 | 21 | 1 | 0 | 0 | 0 | 1 | N | 0 |
| 02 | BG | N | 605 | 7 | 84 | CC | 224 | 0 | 20 | 1 | | 0 | 50 | 0 | 0 | 1 | 11 | 1 | 0 | 0 | 0 | 1 | N | 0 |

*Surface Type : CC-Cement Concrete PS-Polished Stone OPS-Other Pucca Surface MOR-Moorum OTH-Others

Station Name : Ragaul

Summary

(As per Railway Board's Letter No. 2012/LM (PA)/3/5) Dt. 11.09.2012)

| Item -> | Waiting Hall (sqm) | Shelter (sqm) | TAP/HP (nos) | Lavatories (nos) | Urinals (nos) | Seats (nos) | FOB (nos) | Height of Platforms | No of Water Coolers | Signage |
|-------------------|--------------------|---------------|--------------|------------------|---------------|-------------|-----------|----------------------|---------------------|---------|
| Min. Facility | 30 | 100 sqm | 16 | 4 | 4 | 100 | 0 | High level | 2 | - |
| As per Rec. norms | 14 | 0 | 1.32 | 0 | 0 | 4 | | | - | - |
| Actual | 44 | 1159 | 37 | 4 | 4 | 162 | 1 | See platform details | 1 | YES |
| Shortage, if any | - | - | - | - | - | - | - | | 1 | - |